ROHM AND HAAS COMPANY

EMPLOYEE HEALTH AND SAFETY NDEPENDENCE MALL WEST HLADELPHIA, PA. 19105

EMERGENCY PHONE

215-592-3000 (ROHM AND HAAS) 800 -424-9 300 (CHEMTREC)



HAZARD RATING Fire 4 = EXTREME 3 = HIGH 2 = MODERATE <u>Health</u> 1 = SLIGHT 0 = INSIGNIFICANT



hazard) lth hazard) everse side	RDOUS INFORMATION))**	PLASTIC G	TWA/TLV 10 mg/M3* ACGI 10 ppm (ACGIH) *Nuisance dust	
Crylic res	POOUS INFORMATION))**	100	10 mg/M3* ACGI 10 ppm (ACGIH)	
(I. HAZAR MARY hazard) lth hazard) everse side	POOUS INFORMATION))**	100	10 mg/M3* ACGI 10 ppm (ACGIH)	
hazard) lth hazard) everse side)** 2•	100	10 mg/M3* ACGI 10 ppm (ACGIH)	
hazard) lth hazard) everse side		100	10 mg/M3* ACGI 10 ppm (ACGIH)	
lth hazard) everse side			10 ppm (ACGIH)	
Ç 11. 1			*Nuisance dust	
	PHYSICAL DATA		· ·	
dor				
dor		VISCOSITY	* · · · · · · · · · · · · · · · · · · ·	
	; mild acrylic odor		NA	
	YAPOR PRESSURE (MM HG)		VAPOR DENSITY (AIR = 1)	
	NA	NA		
ILE (BY WT.)	specific gravity (water = 1	NA	EVAPORATION RATE (BUTYL ACETATE = 1) NA	
. FIRE AND	EXPLOSION HAZARD DA	TA)		
TEMPERATURE	LOWER EXPLOSION LIMIT	UPPER EXPLOSION	N LIMIT	
rmined	NA Salasa a laga de granda	% NA	97	
	ay create dust hazar sufficient concentr		te or explode.	
	LTH HAZARD DATA			
	HTED AVERAGE CONCENTRATION FOR	R AN 8-HOUR WORK PERIOD		
piratory to may irrital n contact t	e to residual monome ract, and produce sy te the nose, throat with dust may cause can cause eye irrita	mptoms of head and upper resp a localized ir	lache, nausea. oiratory tract.	
	breathing, apply art Call physician. water for at least 1	ificial respir		
	. If not e oxygen.	. If not breathing, apply are e oxygen. Call physician.	. If not breathing, apply artificial respir	

	C V. RE	ACTIVITY DATA	<u>) </u>		
	ABLE contact with	Degrades rapi ignition sour		ter than 4	50F. Avoid
HAZARDOUS DECOMPOSITION PRODU					
Thermal decomposit:	lon: oxides of carbon	, monomer fume	s.	<u> </u>	<u></u> J.
HAZARDOUS POLYMERIZATION					
MAY OCCUR X WILL					
INCOMPATIBILITY (MATERIALS TO					j.
WATER X OTHE		OR LEAK PROCED	URE)		
STEPS TO BE TAKEN IN CASE MATE	RIAL IS RELEASED OR SPILLED				
Keep all unnecessar	ry people away. Removersin powder or dust was posal. Keep spill ou	with water spra	y. Sweepι	ip and plac	e in container
		and the second s			
WASTE DISPOSAL METHODS	oved equipment or land	46411 nono-24no	to current	local et	ate and
Incinerate in appr federal regulation		irili according	, to current	. 10car, 3c	.acc and
	(VII. SPECIAL F	PROTECTION INFO	RMATION		
TYPE VENTILATION					
Mechanical local e	xhaust at point of ha	ndling and use.			
BECRUBE TORY BROTECTION			repolition of the control of the con		
Wear suitable MESA	/NIOSH approved respi	rator where exp	oosure limi	ts are exce	eded.
PROTECTIVE GLOVES	EYE PROTECTION		1、结体有"1011"。		<u> </u>
Impervious	Safety glas	ses with side :	shields (AN	SI Z87.1,	1968)
OTHER PROTECTIVE EQUIPMENT					
Eyewash station					
	VIII, STO	RAGE AND LABEL	ING)	FRATED	OUTDOOR
STORAGE TEMPERATURE		NO	NO		YES
MAX. 140F MIN.	YES	INU	TNO		<u> </u>
Note: Residual mo	nomer content under c apor can be released local overheating can	into workroom	atmosphere	when solld	resins are
	CIX, TOX	CICITY INFORMATI	ON		
NOTE: Crieding or	- milling resin to fir	LANEOUS INFORM le particle siz	e or millir	g finely p	owdered resins
can generate stat:	ic electricity, discha flammable vapors produ ktraction machinery mu	rging can lead ced. Therefor	to ignition, all grin	n or expio	sion of dust/all
NA = NOT APPLICABLE C = CEILING VALUE	THE INFORMATION CONTAINED HER CURATE. HOWEVER, NO WARRANTY THE ACCURACY OF THESE DATA OR USE THEREOF.	THE RESULTS TO BE OBT	AINED FROM THE	DATE OF ISSUE 12/78	SUPERSEDES 11/72
CODE 6-5117	PERSON PROXIMATELY CAUSED BY	TO AS STIBILLATED IN T	E DATA SHEET.	PREPARED BY	KW (
0-311/	PROCEDURES ARE NOT ADHERED ADDITIONALLY, VENDOR ASSUMES NOR THIRD PERSONS PROXIMATELY	A PERSONAL PULL LATY FOR IN	JURY TO VENDEE	Walter	R. Varienak
	I A A WULDE BERSONS PROXIMATELY	TY PROCEDURES ARE POL		- 10	100 1011